

**LEACHATE COLLECTION WELLS
INTERIM OM&M MONITORING AND BAILING DATA SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

DATE: June 22, 2006


TECHNICIAN NAME: Baltazar

TECHNICIAN SIGNATURE 

WELL ID	BOTTOM OF WELL AFTER CONSTRUCT-ED [TOTAL DEPTH] (ft)	MEASURED BOTTOM OF WELL [TOTAL DEPTH] (ft)	GAUGING TIME		DEPTH TO LIQUID (ft)						HEIGHT OF LIQUID COLUMN (ft)		VOLUME OF LIQUID REMOVED (gallons)	COMMENTS
			Start	Finish	Start			Finish			Start	Finish		
					1 st Rdg.	2nd Rdg.	3 rd Rdg.	1 st Rdg.	2nd Rdg.	3 rd Rdg.				
LC-1	22.25													
LC-2	21.90	21.90	1317	1336	13.90	13.90	13.90	21.38	21.38	21.38				
LC-3	22.20													
LC-4	21.90	21.90	1347	1301	13.22	13.22	13.22	21.27	21.27	21.27				

W:\Interim_OM+M\LeachateCollectionWells\WorkPlan+FieldForms\June2006\June2206LC-WellsM&B(YF).doc

**LEACHATE COLLECTION WELLS
INTERIM OM&M INSPECTION SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

INSPECTOR'S NAME	INSPECTOR'S SIGNATURE	INSPECTION TIME	INSPECTION DATE
Baltazar		1300	June 22, 2006

ITEM OF POTENTIAL CONCERN	CONDITIONS OBSERVED				COMMENTS	CHECK (✓) BELOW WHEN COMPLETED
	WELL ID LC-1	WELL ID LC-2	WELL ID LC-3	WELL ID LC-4		
Wellhead (well box, cover, gasket, concrete)		OK		OK		✓✓
Well Casing and Cap/Plug		OK		OK		✓✓
Liquid Present in Well Box		NO		NO		✓✓
Other:						
Other:						
Other:						

W:\Interim_OM+M\LeachateCollectionWells\WorkPlan+FieldForms\June2006\June2206LC-WellInspection(YF).doc

4

TRC
Customer-Focused Solutions

DAILY FIELD REPORT
WASTE DISPOSAL, INC
SANTA FE SPRINGS, CALIFORNIA

FIGURE J.1